

106-108 Boundary Road: Update 23 – Roof rendering, insulation and wiring



External: Photos (a) & (b) Completed rendering at roof level



Internal: Photos (a) & (b) Sound insulation (c) Studwork in 2nd floor flat (hallway outside bedrooms) and (d) insulation, wiring and pipework in the 1st floor ceiling.

106-108 Boundary Road: Update 23 – 2nd Floor Internal



Internal 2nd floor plastering: Photos (a) Front (Master) bedroom ceiling (b) Bathroom ceiling



Internal 2nd floor plastering: Photos (c) Rear (2nd) bedroom ceiling (d) En-suite ceiling and shower tray